






















8163







8163N

NR	ELEMENT	8163N
E1	<div data-bbox="237 566 392 600">D8163_1N</div> 	1
E2	<div data-bbox="231 887 386 920">D8163_2N</div> 	1
E3	<div data-bbox="231 1202 386 1236">D8163_3N</div> 	1
E4	<div data-bbox="231 1518 386 1552">D8163_4N</div> 	1
E5	<div data-bbox="242 1821 399 1854">D8163_5N</div> 	1
E6	<div data-bbox="231 2152 386 2186">D8163_6N</div> 	1



















NR	ELEMENT	8163N
E7	 D8163_7N	1
E8		1
E9		 x3 1
E10		2
E11		1
E12		1


NR	ELEMENT	8163N
E13		1
E14		1
E15		1
E16		1
E17		1
E18		1

NR	ELEMENT	8163N
E19		1
E20		1
E21		1



8163N


Nr	Element	DIN	ELEMENT	Σ
1		-	S6x60	46
2		-	W6x60	41
9		ISO 7380	M6x25	2
10		DIN 9021	6x18	12
11		DIN 1587	M6	2
16		-	K1_d21_B	12
17		-	Z1_d21_B	12
20		DIN 571	8x80 (OC)	12
21		DIN 125	8x16	31
22		DIN 125	6x12	8
24		ISO 7380	M6x16	4
29		-	K_5_A2_g2_ G_v2	6
58		-	LOCTITE	1
77		-	K3_d30_A89 _G	1
90		DIN 125	16x30	14
139		DIN 7991	M6x16	2
146		DIN 7991	M6x12	4
147		-	M6x10	18



8163N


Nr	Element	DIN	ELEMENT	Σ
188		ISO 7380	M6x55	8
213		-	Z_NA_1	1
214		-	Z_NA_2	1
229		-	Z_R_42	7
230		-	S1_8100_0	7
238		DIN 1587	M16	7
264		-	S40_8100_0	3
273		-	S43_8100_0	4
282		-	8100_22_A2 _g4_G_v2	4

# 8163N








PL: "Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu."




1

8163N




2

8163N




INST\_81\_87  
INST\_81\_16  
INST\_81\_63  
INST\_81\_2




3

8163N




INST\_81\_89  
INST\_81\_89G




4

8163N



INST\_81\_124  
INST\_81\_17A  
INST\_81\_164



5

8163N

B25 0,85m<sup>3</sup>

min. 48H

