










8144














8144N

NR	ELEMENT	8144N
E1	 D8144_1N	1
E2	 D8144_2N	1
E3	 D8144_3N	1
E4	 D8144_4N	1
E5		1
E6		1


NR	ELEMENT	8144N



8144 N

Nr	Element			Σ
1		-	S6x60	18
2		-	W6x60	17
10		DIN 9021	6x18	16
13		ISO 7380	M6x20	16
21		DIN 125	8x16	17
58		-	LOCTITE	1
77		-	K3_d30_A89 _G	1
147		-	M6x10	16
213		-	Z_NA_1	1
214		-	Z_NA_2	1
282		-	8100_22_A2 _g4_G_v2	8



8144N



8144N



ENG: „Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.”

PL: “Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu.”




1

8144N




2

8144N



INST_81_188






3

8144N

B25 0,34m³

min. 48H



4

8144N

